
HYVA QUILL SHAFT

QUILL SHAFT



 Hyva
 Partno.:
 021313000

 Gearbox:
 VOLVO



| Parts list | | | | | | | |
|------------|----------|-----------------------------------|---|--|--|--|--|
| No. | Partno.: | Description | | | | | |
| 1 | | Quill shaft | 1 | | | | |
| 2 | | Circlip E 45 | 1 | | | | |
| 3 | | Circlip I 75 | 1 | | | | |
| 4 | | Ball bearing 45x75x16 | 1 | | | | |
| 5 | | Gasket between flange and gearbox | 1 | | | | |
| 6 | | Washer | 4 | | | | |
| 7 | | Nut M12 CH17 H12 | 4 | | | | |
| 8 | | Stud screws M12x28 UNI5911 L=46 | 4 | | | | |
| 9 | | Shift PTO coupling flange | 1 | | | | |
| 10 | | Gasket | 1 | | | | |

| Type of Gearbox | | | | | | | |
|-----------------|-------------------------------|--|--|--|--|--|--|
| VOLVO | R1000SRO2400 / VT1708VTO2814B | | | | | | |



093-01209HY subject to change without notice DO-E 021313000 / 10 10 22 / RV AC

HYVA QUILL SHAFT

QUILL SHAFT




Hyva Partno.: 021313000
Gearbox: VOLVO

Page 2 / 2

General informations

In some cases the VOLVO transmission can have a lubrication hole for the PTO. In this case, pay particular attention to correct gasket orientation.



1) Take out the original rear cover and remove any presence of sealant or painting.



2) Fit in the gearbox the complete quill shaft.



| TIGHTENING TORQUE | | | | | | | | | | |
|-------------------------|------|----|-----|-----|---------|----------|--|--|--|--|
| Thread diameter - Screw | (mm) | M8 | M10 | M12 | UNC 3/8 | UNC 7/16 | | | | |
| Screws and nuts torque | (Nm) | 25 | 50 | 80 | 25 | 60 | | | | |
| Studs torque | (Nm) | 10 | 20 | 30 | 10 | 20 | | | | |

For aluminium gearboxes the tightening torque needs to be reduced by 30%.

Note on the tightening torque: the tightening torques reported are only means as a guide and do not replace the indications given by the vehicle's manufacturer of the gearbox manufacturer.

In order to get more information concerning PTO installation please check the Instructions delivered with the PTO.

093-01209HY subject to change without notice DO-E 021313000 / 10 10 22 / RV AC